sketchthis

How to assemble a Maker Table

Learn how to assemble our CNC cut Maker Table

Written By: Eric Schimelpfenig





- Dowel Jig (1)
- Wood Glue (1)
- 7/16 socket (1)
- Wood Clamps (4)
- Rubber Mallet (1)



PARTS:

- 42 EZ LOK threaded inserts (1)
- Bolts (38)

1/4x20 1 1/2" long

• Bolts (4)

1/4 x 20 3" long

- Washers (42)
- Wood Dowels (10)


1/4" wood

- Leg Halves (4)
- Stretcher Halves (2)
- Corners (8)
- Top (1)
- Front/Rear Panel (2)
- Side Panels (2)
- Bottom (1)

Step 1 — Look at the finished product you're about to assemble.








This guide will show you how to take your already cut Maker Table parts and assemble them into a table just like the one you see here.


Step 2 — Gather your parts






 Gather all of your CNC cut parts. Set them out on your bench. They may need some final sanding here.

Step 3



- Insert the dowels into your legs.
 Before you apply the glue fit the legs together to make sure that they line up well, and they fit flush.
- After you check for good fit, liberally apply wood glue and press the two halves together. Sometimes a gentle tap with a rubber mallet can help.
- A Have a rag or towel handy to mop up any glue that dribbles out.

Step 4



- Clamp both of your leg halves together.
- Follow the instructions on the glue you have used to make sure you allow enough dry time before releasing the clamps.